



Safety overload valve.



Hydraulic stroke limitation.




Automatic spring return of piston.



Manometer

PRESSES

Pressure gauge protected inside the frame. It is positioned at eye level to assist for easy reading.
Different pump options: single or two speed manual, manual-pneumatic and electric pumps, depending on the working speed required.



Screw extension for quick approach and fine adjustment.



Two piston manual pump. Fast approach pump and work pressure pump.

Workbench holds a removable tray. (See PRS line page)


Pneumatic and manually operated pump. The pneumatic control is operated by foot pedal. Legs with bolt holes for fixing to the floor or mounting of wheels.

CAPACITY (t)	20	30	50
A	670	670	670
B	530	530	530
C	1850	1850	1850
D	132	132	132
E	488	488	488
G1	21	17	66
G2	858	854	766
R1	120	120	120
R2	75	75	75
R	195	195	195
Weight (kg)	106	112	145

REFERENCES

Two piston manual pump	PRC20	PRC30	PRC50
Manual and pneumatic hand pump	PRC20NF	PRC30NF	PRC50NF
Manual and pneumatic foot pump	PRC20NF	PRC30NF	PRC50NF

Measures in mm.



Pneumatic and manually operated pump. The pneumatic control is manually operated.

